

AL-7000



Features:

- Units of measurement : meters (m) /hpa

Technical Features

Basic Function	
Measuring Range	0-5000m/580-1040 hpa
Resolution	20m/5hpa
Operating Temperature	-20~60°C
Storage Condition	-30~65°C;<90% RH

- Standard Accessories : Neck Strap +Belt Hook
- Dimension : 85(H) x 68(W) x 28(D) mm
- Weight : 90g

LD-40 / LD-70 / LD-100

Features:

- Area/Volume measurement function
- Pythagorean proposition measurement function
- Add and subtract measurement function
- Continuous measurement function



Specification :

Basic Function	LD-40	LD-70	LD-100
Range	0.05-40m	0.05-70m	0.05-100m
Distance Measurement Precision	±1.5mm		
Measurement Unit Options	mm/in/ft		
Area Volume Funtion	✓		
Volume Measurement Function	✓		
Automatically Cut Off Laser	20s		
Automatic Shutdown	150s		
POWER			
AA 1.5V X 2			

- Standard Accessories : Soft Carrying Case, Manual
- Dimension : 118(H) X 53(W) X 26(D)mm

AL-7010



Features:

- Altitude history & Graphical Display of the last 12 hour altitude readings.
- Total Altitude Gain & Loss
- Max./Min. memory for Altimeter and Barometer Pressure
- Barometer Pressure History & Graphical Display
- Electronic barometer Weather Forecast(Sunny, Slightly Cloudy, Cloudy, Small Rain, Large Rain)
- Pressure Trend Indicators
- Perpetual Calendar with day of week
- 12/24 hour selectable
- Low battery indication

Technical Features

Basic Function	Metric	Imperial	Basic Accuracy
Altimeter	500~9000 Meters	-1600~29500 feet	1 meter / feet
Barometer	300~1100 hPa/mbar	8.84~32.44inHG	1 hPa / mbar (0.01HG)
Indoor Temp.	-10~60°C	14~140°F	0.1°C (0.18°F)
Humidity	20~90% Rh		1% RH
Stop Watch	9hr 59min 59sec.		1/10th Sec. or Sec.

- Standard Accessories : Handy Belt, Manual, Charging Cord
- Dimension : 177(H) x 98(W) x 39(D)mm

